

# Transformer controller



- Controller for three-phase motors.
- 5 stage speed controller via integral knob.
- On/off flashing indicator.
- Line voltage for 3ph controller: 400V.
- Output voltage 3ph unit: 95-145-190-240-400V.
- Max temperature: +40°C.

Description	I nom (A)	T (°C)	Fuse max (A)	Max heat dissipation (W)	IP	Weight (kg)	Dimensions (WxHxD)
R-D-7	7	40	16	110	IP21	15,60	270x323x162

Dimensions in mm